



# UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE  
United States Patent and Trademark Office  
Address: COMMISSIONER FOR PATENTS  
P.O. Box 1450  
Alexandria, Virginia 22313-1450  
[www.uspto.gov](http://www.uspto.gov)

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/064,064	06/06/2002	Shoichi Sawa	086142-0521	3161
22428	7590	08/26/2005	EXAMINER	
FOLEY AND LARDNER SUITE 500 3000 K STREET NW WASHINGTON, DC 20007				SMITH, KIMBERLY S
		ART UNIT		PAPER NUMBER
		3644		

DATE MAILED: 08/26/2005

Please find below and/or attached an Office communication concerning this application or proceeding.



UNITED STATES PATENT AND TRADEMARK OFFICE

---

Commissioner for Patents  
United States Patent and Trademark Office  
P.O. Box 1450  
Alexandria, VA 22313-1450  
[www.uspto.gov](http://www.uspto.gov)

**MAILED**

AUG 26 2005

**GROUP 3600**

**BEFORE THE BOARD OF PATENT APPEALS  
AND INTERFERENCES**

Application Number: 10/064,064

Filing Date: June 06, 2002

Appellant(s): SAWA ET AL.

---


Howard Shipley  
Joann K. Corey  
For Appellant

**SUPPLEMENTAL EXAMINER'S ANSWER**

This is in response to the Remand to the Examiner dated July 27, 2005.

In Response to the Remand to the Examiner dated July 27, 2005, the Examiner apologizes for any vagueness in the Examiner's Answer and provides the following comments in hopes of further clarification.

The figure to the right is an augmented illustration of Figure 4 of the White, US 2,421,228 reference, depicting the "guide groove" and the "key groove". With respect to the mating component as illustrated in Figure 6 of White, it is clearly seen that there are three protrusions (11) extending from the periphery of the mating section. These protrusions are defined as not only the projections as claimed as that in Figure 4 but, at least one of the protrusions is defined as the key which is positioned in the key groove as shown at the right. It is these protrusions which, when positioned in the key groove, prevent relative rotation of the coupling member (reference the mating components as illustrated in Figure 1) as required by the Appellant's claim limitation.



As per the general definition of a "groove", it is noted that Merriam-Webster's Collegiate Dictionary Tenth Edition defines a *groove* to be a long narrow channel (in which *channel* is defined by the same reference as a means of communication or a way, course, direction of action). As can be seen in the Figure above, the guide groove is a long narrow channel (as it has a greater length than width thereby meeting the structural limitation of "narrow") and is further a means of communication or a way, course or direction of action for with the protrusion to

transverse. As such, it is maintained that the structure defined by Figure 4 of White is to be considered a “groove”.

It is again stated that the Examiner realizes the structural differences between the Appellant’s invention and cited references. This is evident by the finding of allowable subject matter in claims 6-9. While the claims are read in light of the Appellant’s specification, it is the claim limitations themselves that define the metes and bounds of the invention being sought for protection. As such, the claims must be interpreted as broadly as their terms reasonably allow. With the clarification of the Examiner’s reading of the prior art stated herein, it is respectfully submitted that the combination of references with proper motivation for combining, define the structural limitations as those claims currently on Appeal.

#### Reply Brief

In response to the Reply Brief filed January 27, 2005:

The Appellant’s argue that axial movement of the lugs 11 only occurs after the lugs 11 are inside and mated with the bayonet slots 6. In view of the Figure submitted above, it is clearly seen that there is an axial component to the movement of the protrusion within the guide groove prior to insertion into the key groove. It is noted that within the structure of claims 1 and 10, it is the groove to which the Appellant has defined the area in which the projection rests thereby preventing the receiving member and the bottle from moving apart. In the combination of references as applied, it is only within the key groove that this limitation is met and thereby,

Art Unit: 3644

there is an axial component to the movement of the protrusions within the guide groove prior to mating with the key groove.

With respect to the statement regarding claims 1, 10 and 20 directed to the projections of White not extending only partially around the periphery of the connection. As can be seen in Figure 4 of White, there are three grooves (6) into which projections (11) are inserted. These grooves are clearly shown to lie within the same plane. As such, it is inherent that the protrusions (11) to which they are to mate must also lie in the same plane. Given this fact, the protrusions (11) are considered to lie on the periphery of the connector at a distance measured by their diameter, which is less than the entire periphery. If the projection were extended around the entire periphery of the connection (which is the opposite of the claimed limitation of extending only partially around the periphery of the connection), the fitting would not be able to be coupled within the groove (6). Therefore, it is maintained that the protrusions extend only partially around the periphery of the connection.

With respect to the Arguments of Claims 2, 11 and 17, reference discussion above with respect to the issues raised on Remand.

With respect to the Argument of Claim 4, the Examiner agrees with the Appellant and withdraws the rejection regarding Claim 4 as well as dependent Claim 5.

For the above reasons, it is believed that the rejections should be sustained.

Respectfully submitted,

Kimberly S Smith  
Examiner  
Art Unit 3644

kss  
August 17, 2005

Conferees  
Teri Luu   
Michael Carone 



TERI PHAM LUU  
SUPERVISORY  
PRIMARY EXAMINER

FOLEY AND LARDNER  
SUITE 500  
3000 K STREET NW  
WASHINGTON, DC 20007



APPROVED BY  
DONALD T. HAJEC  
DIRECTOR, TECHNOLOGY CENTER 3600